



Note:  
 IF LEVEL SENSOR AND LOW LEVEL OPTION NOT USED  
 CAN TAKE +12 VDC FROM J7 PIN 1  
 AND 0 VDC FROM J7 PIN 4



FLOW METER



PROJECT: FUELLOX		DRAWING TITLE: Fuellox ( +12VDC input) Wiring Diagram PS-100 Flow meter
DRAWN BY: Paul Jenkins		
SHEET: 1 OF 1	STATUS:	
DATE: 2019-07-10	(c) IOTIQ	